

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>GU - Agana</i>				
Ciao	High	Grounded; 41' sailboat Grounded sailboat.	N: 13.4784 E: 144.7503 Sandy bottom with coral rubble, gravel and riprap shoreline.\wgs84	AVP
Lion's Den	High	Derelict; sailboat Two masted sailboat sunk between AVP visits in 2002 and 2003.	N: 13.4790 E: 144.7501	AVP
Unk1900 - Ferro- Cement Sailboat	High	Sunk; 35' sailboat Derelict vessel moored in marina. Could be a problem in the future.	N: 13.4790 E: 144.7510 was moored at marina and sunk wgs84 Sandy bottom with coral rubble, gravel and riprap shoreline. Some large corals growing on	AVP
Unknown2539 - Steel sailboat	High	Sunk; 55' sailboat Steel sailboat agound / sunk.	N: 13.4780 E: 144.7500 Sandy bottom with coral rubble, gravel and riprap shoreline. Wgs84	AVP
Unknown2540 - sailboat	High	Sunk; 25' sailboat Medium sunken fiberglass sailboat.	N: 13.4780 E: 144.6860 WGS84 Sandy bottom with coral rubble, gravel and riprap shoreline.	AVP
Windsong	High	Sunk; 27' sailboat Medium sized sailboat.	N: 13.4780 E: 144.7500 Agana Boat Basin wgs84 Sandy bottom with coral rubble, gravel and riprap shoreline.	AVP

GU - Apra Harbor

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>GU - Apra Harbor</i>				
Breakwater Barge	High	Other; barge Commonly know barge near the breakwater in Apra Harbor.	S: 0 W: 0	common
Polaris Sailboat	High	Sunk; sailboat	N: 13.447 E: 144.670	individual
<i>GU - Apra, Piti</i>				
Chamorro I	Medium	Grounded; 49' fishing Overturned longliner	N: 13.4622 E: 144.6855 Actual fix Registration #59103	AVP
Crystal Be???	Medium	Sunk; sailboat Partially submerged sailboat.	N: 13.4626 E: 144.6848 actual fix	AVP
Dolphin Dancer	High	Sunk; 26' sailboat Sunken Sailboat - in large cluster of wrecks.	N: 13.4628 E: 144.6853 actual fix	AVP
Guahan One	High	Derelict; 100' landing craft Larege, abandoned landing craft.	N: 13.4606 E: 144.6725 Sand and gravel bottom with lagoonal fauna - including small corals. Vessel is also right up against mangroves. Outer Piti Channel on North	AVP

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>GU - Apra, Piti</i>				
Guahan Two	Low	Derelict; 115' landing craft Derelict commercial steel vessel.	N: 13.4626 E: 144.6853 in the back of the channel	AVP
Lady Catherine	High	Grounded; 58' fishing Stranded longliner - relatively intact.	N: 13.4640 E: 144.6877 over a small culvert actual fix	AVP
Merlin	High	Derelict; 41' sailboat Fiberglass ketch totally up on the beach.	N: 13.4620 E: 144.6854 actual fix completely ashore - up on the beach	AVP
Piti Crane Barge	High	Grounded; 100' barge Crane barge abandoned in cluster with three other vessels.	N: 13.4604 E: 144.6734 Sand and gravel bottom with lagoonal fauna - including small corals. Vessel is also right up against mangroves.	AVP
Piti Dive Barge	High	Derelict; 39' barge Salvage vessel that was wrecked in a storm	N: 13.4627 E: 144.6844 actual fix	AVP
Piti Marina	High	Derelict;	S: 0 W: 0	individual

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>GU - Apra, Piti</i>				
Piti Sailboat Bow	High	Grounded;	S: 0 W: 0	
Unk1906 - small LC	Medium	Sunk; 55' landing craft Small landing craft in large cluster of wrecks.	N: 13.4626 E: 144.6856 Actual fix	AVP
Unk1909 - frieghter	High	Grounded; 120' cargo/supply Small derelict frieghter.	N: 13.4604 E: 144.6734 Sand and gravel bottom with lagoonal fauna - including small corals. Vessel is also right up against mangroves. Outer Piti Channel on North	AVP
Unknown2523 - sailboat	High	Grounded; 21' sailboat Small sailboat - stranded.	N: 13.4638 E: 144.6877 back of piti channel - accessed across power plant property. Actual fix	AVP
Unknown2527 - sailboat	Medium	Sunk; 35' sailboat Sailboat full of rubble.	N: 13.4624 E: 144.6854 directly along side AH5	AVP
Unknown2528 - Ketch	Medium	Sunk; 53' sailboat Large ketch lying right next to Guahan 2.	N: 13.4625 E: 144.6856 directly along side of AH5 - on port side actual fix	AVP

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

GU - Apra, Piti

Unknown2529 - landing craft	Medium	Sunk; 50' landing craft Landing craft sunk with other vessels in large cluster.	N: 13.4624 E: 144.6854 fix for Guahan2 - this vessel is on shoreline behind it - mostly submerged	AVP
Unknown2531 - barge	Low	Grounded; 67' barge Derelict barge - in cluster with 3 other vessels.	N: 13.4604 E: 144.6734 Sand and gravel bottom with lagoonal fauna - including small corals. Vessel is also right up against mangroves. Fix for 2530	AVP
Unknown2536 - trimaran	High	Wreck; 41' sailboat - trimaran Wrecked trimaran in marina.	N: 13.4611 E: 144.6838 sand and gravel - vessel is in marina	AVP
Unknown295	High	Grounded; 45' other	N: 13.461 E: 144.678	AVIS

GU - Cocos Lagoon

Unknown2542 - Sailboat	High	Grounded; 20' sailboat Small wrecked sailboat high and dry on beach.	N: 13.2670 E: 144.6650 WGS84	AVP
---------------------------	------	--	---------------------------------	-----

GU - Sasa Bay

Abandoned Vessel Inventory

Vessel List :GU
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>GU - Sasa Bay</i>				
Seagull	High	Grounded; 70' sailboat Large ketch blown ashore over reef. Currently salvage is in the permitting stages.	N: 13.4450 E: 144.6810 Mud flat wgs84	AVP