



Update on Season's Field Activities

St. George Island RAB Meeting
June 16, 2004



Areas Revegetated Spring 2004

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Data from Pribilof
Project Database



Legend

◆ Points of Lead Contamination



Figure

1

2004 Field Season Lead Cleanup Locations

Source: Aero Map 9/28/96
Aerial Photograph; Samples
from Pribilof Project Office
Database






Figure

1

**City of St. George/Public Health
Service Septic System Installation**

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Data from Pribilof
Project Database





Figure

2

**City of St. George/Public Health
Service Septic System Installation
Open Pits PCS Stockpile**

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Data from Pribilof
Project Database





Figure


9

**Historic Site Profile
TPA 9, Old Power Plant
St. George Island, Alaska**

04/01/04

Source: 1961 Photo from NOAA
Pribilof Project Archives






Figure

7

**Estimated Extent of Contamination
TPA 9 (Old Power Plant)
Over 1948 Ground Conditions**

Source: 1948 Victor Scheffer Aerial Photograph; DRO Estimated Extent from Pribilof Project Database





Figure

5

**Site Utility Plan
TPA 9, Old Power Plant
St. George Island, Alaska**

04/01/04

Source: Hart Crowser 1996 Expanded Site Inspection; Historic Aerial Photos; Pribilof Project Database





PCS Disposal Update





Figure

2 - 1

PCS Transportation Route to New St. George Landfill


Source: Ikonos 2001 Satellite Image; Survey Data from Pribilof Project Database





Groundwater Sampling Results





● Groundwater Monitoring Well

St. George, Alaska in 3D Perspective

Diesel Range Organics (DRO) in Groundwater, St. George, Alaska

